	WATER TESTING FORM	Page _ l _ of _ 4			
Sewershed: Low Level Subsewershed: Lh 36	Company: Savin	Date: <u>8/12/08</u>			
Test Type: Smoke X Dy Water	/ed Ground Condition: Dry:x_Damp: Wet:	_ Supervisor: Rich Trask			
Manhole ID: 19m 020	Test ID: <u>/029 -062 -0/</u>	Crew: 01  Notifications Made: X			
Field Sketch: (Show all manholes with	numbers, blower placement location, sandbag				
building addresse	es and locations, defect locations and photogra	aph numbers)			
1//////////////////////////////////////		'   H			
////////////////////RAI	MSAY ST	007			
////		025 007			
pulaski	22	50			
7/5					
339 339	004	TON ST			
S	AS'	HTON ST 401			
	R: (156)	The state of the s			
249	The state of the s	400			
	138	406 S			
		408			
		406 406 408 408 410 416 416			
	106   3 5 5 1   Brune	416			
100	a BEE	12			
403		E B			
407	1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	B HEATT			
411	046 6 1 1 1 1 1 1 1 1	013			
1313	TE COLOR	\$28			
419	037	330			
11110000	AZS CHRISTIAN	13/4			
-1////		436			
		857			

			TIMORE WE						E		Pag	e2	2_ of _4_
	Sewershed	l: Lo	w Level	T T				: Savin			Da	ate: (	8/12/08
	Subsewers			<u> </u>									<u> </u>
est	Type: Smok Water		X Dyed					ondition: Wet		-			Rich Traskos
	Manhole II	D: <u>1</u> 9	9M 020		Test	ID: _1	1029	<u>062</u>	01			Crew:	
AUDIT C	iaid Skatah: /St	OU O	Il manholes with	numb.	ore blower	nlago	mont	location so	ndhaa	orico	Notificat		
1	iain avaicii. (ai		building addresse									UI 15, 51	ueet names,
Def	ect		ddress		Source		ation			nage			
No	о.		address		Туре	LOC	auon	Sector	A	rea	Seventy	Ph	oto Number
1			. Payson St.		03		8	02		10	03		341
2			Christian St.		03		8	02		50	03	Ь—	342
3	<u> </u>		Pulaski St.		03		8	02		0	02	Ь—	343
4	20	)02 (	Christian St.		03	0	8	02	1	10	02	ļ	344
-									<u> </u>			├─	
<del> </del>								<del>                                     </del>	-				
	<del>-  </del>				<del> </del>	<b></b> -		<del> </del>	<del>                                     </del>			<del>                                     </del>	
						-		<del>                                     </del>	<del> </del>		<u> </u>	<del></del>	
						<del></del>			<u> </u>			$\vdash$	
								<del></del>					
				•									
									<u> </u>				
									<u> </u>			<u> </u>	
ļ									ļ				
<u> </u>							-						
												-	
								1				_	
			· · · · · · · · · · · · · · · · · · ·					<u> </u>				<del></del>	
	<u> </u>		···					1				<del>                                     </del>	
<b></b> -	<del>-                                     </del>							<del> </del>		<del></del>		<b></b>	
								<u> </u>					<del></del>
									İ				
Ab					OBSERV		_		T) until				
Source Type		04	Davis d O		ation				ector		Severity		
	Main Sewer		MH Frame		Paved C	onc.					Public		No Smoke
	Service Line Cleanout	_	Storm Drain Catch Basin		Asphalt Paved O	ther		Field/Wo	ous	02	Private		Trace Moderate
	Downspout		Storm MH		Driveway			Golf Cou	rse	<b></b>			Major
	Area Drain		Storm Ditch		Sidewalk			Other	136	<u> </u>			iviajoi
	Dwy. Drain		Excavation		Curb	•	, <del>,,</del>	J. 1.01		<b></b>			
	Stair. Drain		Water Line		Yard - Fr	ont				<u> </u>			
	Found. Drain		Tele. Pole		Yard - Ba								
	Bldg. Interior		Other	_	Yard - Si								

	VATER TESTING FORM	Page <u>3</u> of <u>4</u>
Sewershed: Low Level Subsewershed: LL36	Company: Savin	Date: 8/12/08
est Type: Smoke X Dyed Water	Ground Condition: Dry: X Damp: Wet:	Supervisor: Rich Trask
Manhole ID: 19M 020	Test ID: <u>1029</u> <u>062</u> <u>01</u>	Crew: 01 Notifications Made:X
	mbers, blower placement location, sandba and locations, defect locations and photog	
		X THE
	7271	
200000000000000000000000000000000000000		
10	29-062_OB01-01	
	Salah Sa	
24		
		1
		the ball of the second
1	The state of the s	
2, 3, 3		7 75
		THE RESIDENCE OF THE PARTY OF T

